


INSTRUCTIONS & INFORMATION



623710, 623711, 623712

(Sheave height spacers are no longer included in Spindle Assemblies)



Item No.	Order No.	Description
1	623764	Blade Spindle Assembly
2	623732	Blade Spindle Assembly
3	623765	Blade Spindle Assembly
4	623768	Blade Spindle Assembly
5	243331	Hex Bolt
6	257041	Washer - Cupped
7	110081	Bearing - Ball
8	604418	Housing Assembly
9	280745	Grease Fitting
10	903643	Bearing Spacer
11	604773	Spindle Shaft Assembly
12	604774	Spindle Shaft Assembly
13	604775	Spindle Shaft Assembly
14	421200	Washer - Fiber
15	257061	Washer
16	257057	Washer - Hardened
17	243583	Hex Bolt
18*	282607	Spacer
19	257055	Washer
20	423680	Deflector Cone
21	721167	Bearing Shield
22*	257104	Washer
23*	281582	Square Key
24*	281583	Square Key
25	247141	Stud Bolt
26	253192	Stud Bolt
27*	282615	Spacer

* NOT INCLUDED WITH SPINDLE ASSEMBLIES